

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Monument \_\_\_\_\_

Location filed \_\_\_\_\_

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Subsequent Corner Restoration

Species Tam 5"  
Diameter 575w  
Bearing N1W  
Distance 8045

Bearing Trees

Year surveyed 1876  
Original monument lost

Original Government Survey

EXISTING SURVEYS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_


Bearing Trees, Reference Objects

Index No. N19

CASS COUNTY LAND CORNER RECORD

T. 144 R 25 M. 5TH Coordinates: X 14,23 Y \_\_\_\_\_

Corner common to sections 14,23



Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set obliterated - 5/8" x 8' aluminum rod w/cap  
5" Cedar S87E 7.35'  
6" Tam S45W 18.40'  
6" Cedar N80W 10.13'  
Doc. # 281945

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_