


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey
Year surveyed 1876
Original monument Post

Original Evidence Found
Year of search _____ by _____
Monument found _____

Bearing Trees
Species Cedar Birch
Diameter 5" 8"
Bearing S 60° W N 62° W
Distance 25 links 21 links

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location
Monument: Set 5/8"x 36" aluminum rod monument with cap, down 0.3' at lost position, on center line County Road #3.

Evidence of Subsequent Corner Restoration
Year of search 12/1983 By J.R. Worcester, CCHD
Location filed: S.P. 11-603-07
Monument: Indicates corner assumed at Station 258+49.8

Bearing Trees, Reference Objects
Species N. Pine Maple
Diameter 12" 8"
Bearing N 21° E S 45° E
Distance 71.20' 93.80'

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 7/2011 By CCHD/SO
Location filed: #2011.015
Monument: Set P.K. from 1984 witnesses, on center line of CSAH #3, 3'+, - west of fence line to south and add the following:
Steel post, S 3° W, 62.3'(1984)

8/2011, CCHD/SO
#2011.015
Set Mag nail from witnesses after construction, 0.5' south of new center line CSAH #3.

7/2019, CCHD/SO
#2011.015
Found Conc. nail, 0.5', S. of centerline CSAH #3 and witness, 14" N. Pine, N 21° E, 71.20'(1985) 20d nail, up 2.7', W. side
10" Maple, S 45° E, 93.80'(1985) 20d nail, up 3.5', S. side
Steel Sign Post, S 3° W, 62.3 (2011)
10" Maple, N 40° W, 94.88' duplex nail, up 1.2', E. side

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651788
Filed on the above information.

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
Location filed: _____
Monument: _____

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Monument _____
Location filed _____
Year surveyed _____

By _____

Subsequent Corner Restoration

Species Cedar 5"
Diameter 5"
Bearing 56W
Distance 25 LKS

Bearing Trees

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

Original Evidence Found _____
Year of search By _____
Monument found _____
Original Bearing Trees Found _____

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration


Year of search _____
By _____

Bearing Trees, Reference Objects

Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 194 R. 25 M. 57H Coordinates: X 2932 Y _____
Corner common to sections 2932 N 1/4 32



Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set 5/8 x 36" aluminum rod w/ stamped cap
12" N. Pine N21E 71.20'
8" Maple S45E 93.80'
Doc. # 281973

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Re monumentation certificate prepared _____

By _____

Filed at _____

Date _____