


T. 144 R. 26 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 34 Corner common to sections 26, 27, 34, 35  
imc #6



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1875  
Original monument Post

**Bearing Trees**

Species	<u>Elm</u>	<u>Willow</u>	_____
Diameter	<u>18"</u>	<u>4"</u>	_____
Bearing	<u>N60E</u>	<u>59E</u>	_____
Distance	<u>32 Ls</u>	<u>47 Ls</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1919 By JAMES FLYNN  
Location filed COUNTY BOOK "C" P. 176  
Monument FIND OLD GOVT B.T. : ELM STUMP N60E  
14.5'  
1919, JAMES FLYNN, COUNTY BOOK "C" P. 179 FIND  
ELM B.T SET 1 1/2" x 4" IRON MILL SHAFT

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Evidence of Subsequent Corner Restoration**

Year of search 1922 By GLO  
Set 2x36" l.p. Wilbruss cap at E. end of old fence  
made from orig B.T.S T149N R26W  
527 | 526  
mc  
534 | 535

**Bearing Trees, Reference Objects**

<u>Ash</u>	_____	_____	_____
<u>6"</u>	_____	_____	_____
<u>N74-15'E</u>	_____	_____	_____
<u>304 Ls</u>	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1953 By DNR-Engineering  
Location filed Notes and map in file  
Monument Found Corner?

1959 - DNR - notes in file  
set R.R. spike

Marks in end of culvert  
- E. end 35.53' NE  
- W. end 29.28' NW

Access sign post SW 28.40'

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - MUD LAKE PASS  
JAMES H. FLYNN 1926

1999 - CCSD  
REF. TIES:  
P.K. in top of fc. post S 85°W 23.05'  
" " " " " S 40°E 53.24'