


T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
NE32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees		
Species	<u>Br. Oak</u>	<u>Br. Oak</u>
Diameter	<u>8"</u>	<u>12"</u>
Bearing	<u>N5E</u>	<u>S10W</u>
Distance	<u>1508 LKS</u>	<u>425 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1922 By GLO
Location filed Sec. of State
Monument End SW B.T. set 2x36" I.P. w/ brass cap
T144N R26W
S29/S28
S32/S33
1922

Evidence of Subsequent Corner Restoration

Year of search 1970 By Milo Stefan
Found GLO monument in good condition.
Set 4" x 4" x 84" Cedar post North 2.40'

Bearing Trees, Reference Objects		
Species	<u>Br. Oak</u>	<u>Br. Oak</u>
Diameter	<u>12"</u>	<u>30"</u>
Bearing	<u>N4-45E</u>	<u>S22-15W</u>
Distance	<u>1663 LKS</u>	<u>521 LKS</u>

Bearing Trees, Reference Objects		
Species	<u>OAK</u>	_____
Diameter	<u>12"</u>	_____
Bearing	<u>S88W</u>	_____
Distance	<u>440.20'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1970 - FILED IN 1979
Doc. # 246232