


T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>Spruce</u>	<u>Pine</u>
Diameter	<u>10"</u>	<u>16"</u>
Bearing	<u>S60W</u>	<u>N80 1/2 E</u>
Distance	<u>30 LKS</u>	<u>39 LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument End NE B.T - Now 30" Set 1x36" 1/4  
with brass cap  
59/510  
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument in good condition.

	Bearing Trees Reference Objects	
Species	<u>White</u>	<u>White</u>
Diameter	<u>30"</u>	<u>18"</u>
Bearing	<u>S80E</u>	<u>N20W</u>
Distance	<u>10 LKS</u>	<u>29 LKS</u>

Bearing Trees, Reference Objects	
<u>Elm</u>	<u>Elm</u>
<u>8"</u>	<u>10"</u>
<u>S42E</u>	<u>N18W</u>
<u>77.7'</u>	<u>37.4'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966