


T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1876  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	Cedar	Cedar	Tam	Tam
Diameter	6"	4"	4"	6"
Bearing	N34W	N9E	S7W	S60E
Distance	36 LKS	29 LKS	65 LKS	115 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1937 By GLO  
 Location filed Sec. of State  
 Monument Set concrete man. 2' long 6" dia w/bress  
cap T144N R27W  
59 | 510  
516 | 515

Evidence of Subsequent Corner Restoration  
 Year of search 1966 By William Okerman  
 Found GLO monument in good condition.

Species	Bearing Trees, Reference Objects			
	Tam	Poplar	W. Pine	N. Pine
Diameter	8"	12"	8"	14"
Bearing	N69 3/4 E	S87 E	S79 1/4 W	N86 1/2 W
Distance	64 LKS	211 LKS	223 LKS	222 LKS

Bearing Trees, Reference Objects				
B. Pine	Spruce	Tamarack	Balsam	Poplar
20"	8"	10"	16"	12"
N18 1/2 W	S62 W	N18 W	N84 E	S72 E
146.52'	176.3'	74.3'	137.0'	147.5'

(1937 BT)

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966