


Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 19 Corner common to sections 17, 18, 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>10"</u>	<u>4"</u>
Bearing	<u>N14E</u>	<u>S11E</u>	<u>N12W</u>	<u>S30W</u>
Distance	<u>16 LKS</u>	<u>17 LKS</u>	<u>9 LKS</u>	<u>15 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLB  
Location filed Sec. of State  
Monument Set Concrete mon 2' long 6" dia w/  
brass cap 7144N R27W  
518/517  
519/520

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects 1937

Species	<u>Poplar</u>	_____	_____	_____
Diameter	<u>7"</u>	_____	_____	_____
Bearing	<u>S84E</u>	_____	_____	_____
Distance	<u>28 LKS</u>	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gary Stevenson - 1982  
Doc. # 264938  
Found GLO monument in good condition  
4" Balm of Gilead S88E 152.4';  
STEEL sign post S82W 7.8';  
STEEL sign post South 2.0';  
STEEL sign post East 3.1';  
STEEL sign post N45E 7.8'.

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_