


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Species	Bearing	Tree	Distance
<u>Ash</u>	<u>7"</u>	<u>Poplar</u>	<u>28 LKS</u>
<u>Poplar</u>	<u>10"</u>	<u>Poplar</u>	<u>21 LKS</u>
<u>Maple</u>	<u>6"</u>	<u>Poplar</u>	<u>34 LKS</u>
<u>Maple</u>	<u>6"</u>	<u>Maple</u>	<u>31 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK # P 230-233

Monument ESTABLISH CORNER FROM OLD GOVT B.T.S. 7" OAK
5.53 E 18.5'; 9" POPLAR N33W 22.4'; 10" POPLAR N67E
13.4'; 6" MAPLE S52W 20.5'

Evidence of Subsequent Corner Restoration

Year of search 1926 By GLO

Set 2x36" l.p. willow sap T144N R29W
517/516
520/521
1926

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>W. oak</u>	<u>6"</u>	<u>Maple</u>	<u>64 LKS</u>
<u>Maple</u>	<u>12"</u>	<u>Maple</u>	<u>34 LKS</u>
<u>W. oak</u>	<u>12"</u>	<u>W. oak</u>	<u>12 LKS</u>
<u>Poplar</u>	<u>8"</u>	<u>Poplar</u>	<u>23 LKS</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1963

Found GLO monument in good condition

5" MAPLE N87 1/2 W 44.35';

8" OAK N20E 42.75';

11" OAK S17W 44.4';

17" W. PINE S35E 67.7'

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____