


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

		Bearing Trees			
Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	
Diameter	<u>6"</u>	<u>8"</u>	<u>6"</u>	<u>7"</u>	
Bearing	<u>S42W</u>	<u>N40W</u>	<u>S25E</u>	<u>N22E</u>	
Distance	<u>32 LKS</u>	<u>43 LKS</u>	<u>26 LKS</u>	<u>11 LKS</u>	

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1923 By HORACE DUNAWAY  
 Location filed COUNTY BOOK D P 127  
 Monument SET 1 1/2" IRON PIPE

Evidence of Subsequent Corner Restoration  
 Year of search 1926 By GLO  
Find granite stone & NE, SE & SW B.T. stumps  
Set 2x36" l.p.w / brass cap T144 N R29 W  
529 | 528  
532 | 533  
1926

		Bearing Trees, Reference Objects			
Species	<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	
Diameter	_____	_____	_____	_____	
Bearing	<u>NW</u>	<u>SW</u>	<u>SE</u>	<u>NE</u>	
Distance	<u>16.5'</u>	<u>25.6'</u>	<u>24.8'</u>	<u>26.3'</u>	

Bearing Trees, Reference Objects  
Tam  
6"  
S25-30W  
86 LKS

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER 1963  
Found GLO monument in good condition  
14" Tamarack S82E 204.55'

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_