


T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NW 1/16 Corner common to sections 1



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor NW1/16 S1  
Original monument Set 1"x 36" iron pipe w/brass cap 1930

Original Evidence Found

Year of search 1936 by CCC  
Monument found GLO iron  
Form 874-9

Bearing Trees

Species	<u>Oak</u>	<u>Birch</u>	_____
Diameter	<u>12"</u>	<u>5"</u>	_____
Bearing	<u>S 82° E</u>	<u>S 71° W</u>	_____
Distance	<u>92 links</u>	<u>96 links</u>	_____

Original Bearing Trees Found

Species	<u>Birch</u>	<u>Oak</u>	_____
Diameter	<u>6"</u>	<u>11"</u>	_____
Bearing	<u>S 18° E</u>	<u>S 7° E</u>	_____
Distance	<u>95 links</u>	<u>92 links</u>	_____

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Folsom, CCC  
Location filed: Form 874-9  
Monument: Found metal pipe up 5" in good condition and GLO witnesses.

Evidence of Subsequent Corner Restoration

Year of search 6/1969 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 14  
Monument: Found 1" GLO iron pipe with brass cap and original Oak witness stump and marked new witnesses as follows.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>White Oak</u>	<u>White Oak</u>	<u>White Oak</u>	<u>Cedar Post</u>
Diameter	<u>7"</u>	<u>8"</u>	<u>8"</u>	<u>4"</u>
Bearing	<u>N 77° W</u>	<u>N 63° E</u>	<u>S 21° E</u>	<u>South</u>
Distance	<u>52.77'</u>	<u>58.78'</u>	<u>37.25'</u>	<u>4.4'</u>

Subsequent Corner Restoration

Year surveyed 9/1983 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 14  
Monument: Found 1" GLO iron pipe with brass cap bent and out of position, straighten and reset from GLO stump and 1969 witnesses, now up 8" and witnesses as follow.  
9" White Oak, N 65° E, 58.60'(1969) 50d spike  
9" White Oak, N 75° W, 52.85'(1969) 50d spike  
10" White Oak, S 17° E, 37.40'(1969) 50d spike

Evidence of Subsequent Corner Restoration Found

Year of search 12/2018 By D.J. Warner, LS 42656  
Location filed: Certificate of Survey for Rounsville, #8744  
Monument: Indicates monument found.  
12/2018, T.L. Freeman, LS 21367  
Certificate of Survey for Peterson, #8743  
Indicates monument found.

9/1983, M.C. Hayes, LS 20774  
USFS Book 1, page 14  
Found GLO monument, at S. edge small swamp, 130'+/-, N. of Pipeline, 370'+/-, S. of FR 2135, removed Cedar post, added.  
Steel Sign Post, North, 4.75' 54-2 and 54-9 signs  
Steel Sign Post, South, 4.80' 54-2 and 54-9 signs  
4" Cedar Post, North, 394.3'


6/1989, G.H. Stevenson, LS 12684  
Certificate of Survey for Lennox, #1307  
Indicates USGLO Brass cap monument in place.

5/1995, T.L. Freeman, LS 21367  
Certificate of Survey for Lennox, #6094  
Indicates USFS Brass cap monument found.

Index No. B 22

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 1/4 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930  
Original monument 1x36" IP. w/bress cap NW 1/4 S1  
1930

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Bearing Trees	
Species <u>Oak</u>	<u>Birch</u>
Diameter <u>12"</u>	<u>5"</u>
Bearing <u>S82E</u>	<u>S71W</u>
Distance <u>92 Lks</u>	<u>96 Lks</u>

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1969 By William Okerman  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>Cedar post</u>
Diameter <u>7"</u>	<u>8"</u>	<u>8"</u>	<u>4x4x72"</u>
Bearing <u>N77W</u>	<u>N63E</u>	<u>S21E</u>	<u>South</u>
Distance <u>52.77'</u>	<u>58.78'</u>	<u>37.25'</u>	<u>4.40'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1969

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_