


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



20

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Minn. Hist. Society, notes pg 117

Bearing Trees

Species	<u>Sugar</u>	<u>Red Oak</u>	<u>White Birch</u>	<u>Lynn</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>16"</u>	<u>6"</u>
Bearing	<u>S 53° W</u>	<u>N 28° W</u>	<u>N 29° E</u>	<u>S 39° E</u>
Distance	<u>6 links</u>	<u>30 links</u>	<u>40 links</u>	<u>17 links</u>

Original Bearing Trees Found

Species	<u>White Birch</u>	_____	_____	_____
Diameter	<u>21"</u>	_____	_____	_____
Bearing	<u>N 29° W</u>	_____	_____	_____
Distance	<u>40 links</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes pg 117 T144N R30W
Monument: Set 6"x26" concrete with brass cap S17 | S16
up 4", from original witness tree and marked S20 | S21
new witnesses trees as follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 11/1966 By J. Ekstrom, USFS
Location filed: USFS Book 1, page 12
Monument: Found brass cap in cement
and notes witnesses as follow.
Steel Sign Post, West, 8.7' 54-4 sign

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>	<u>Maple</u>	<u>Basswood</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N 25 3/4° E</u>	<u>S 79 3/4° E</u>	<u>S 66 1/4° W</u>	<u>N 50° W</u>
Distance	<u>70 links</u>	<u>84 links</u>	<u>43 links</u>	<u>33 links</u>

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>	<u>Maple</u>	<u>Maple</u>
Diameter	<u>14"(1930)</u>	<u>15"(1930)</u>	<u>10"(1930)</u>	<u>6"</u>
Bearing	<u>N 25° E</u>	<u>S 79° E</u>	<u>S 66° W</u>	<u>S 46° E</u>
Distance	<u>43.2'</u>	<u>55.44'</u>	<u>23.38'</u>	<u>37.5'</u>

Subsequent Corner Restoration

Year surveyed 3/1992 By G. Brama, USFS
Location filed: USFS Book 1, page 12
Monument: Found GLO brass capped concrete monument
up 1", 280' W. of Cuba Hill Rd. and witnesses as follow.
12" Maple, S 66° W, 28.38'(1930)
15" Maple, N 25° E, 46.20'(1930) not in good condition
16" Maple, S 79° E, 55.44'(1930)
5" Maple, N 46° W, 37.5'(1966)
Steel Sign Post, West, 8.7'(1966)
12" Red Oak, N 85° E, 41.57' scribed, 60d spike
Steel Sign Post, East, 3.45' sign
20" Maple, East, 265' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
NE20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>Sugar</u>	<u>R. Oak</u>	<u>W. Birch</u>	<u>Lynn</u>
<u>8"</u>	<u>10"</u>	<u>16"</u>	<u>8"</u>
<u>S53W</u>	<u>N28W</u>	<u>N29E</u>	<u>S39E</u>
<u>6LKS</u>	<u>30LKS</u>	<u>40LKS</u>	<u>17LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed SEC. OF STATE
Monument End NE Pt. - new 21" set concrete mon.
26" long 6" dia w/ brass cap T144N R30W
S17 S16
S20 S21

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Bearing	Distance	Reference Objects
<u>Maple</u>	<u>Maple</u>	<u>Maple</u>	<u>Basswood</u>
<u>14"</u>	<u>12"</u>	<u>8"</u>	<u>8"</u>
<u>N25 1/4 E</u>	<u>S79 3/4 E</u>	<u>S66 1/4 W</u>	<u>N50 W</u>
<u>70 LKS</u>	<u>84 LKS</u>	<u>43 LKS</u>	<u>33 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>6"</u>	<u>S46 E</u>	<u>37.50'</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____