


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
S 1/16 Corner common to sections 29, 30



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor S1/16
Original monuments Set 1"x 36" iron pipe w/brass cap S30|S29
1930

Original Evidence Found

Year of search 19704 by USFS
Monument found GLO iron
Certificate of Location

Bearing Trees

Species	<u>Red Oak</u>	<u>Poplar</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>N 4 1/4° E</u>	<u>N 44 1/2° W</u>	_____
Distance	<u>82 links</u>	<u>62 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By C. Schluter, USFS
Location filed: Certificate of Location
Monument: Found iron with brass cap

Evidence of Subsequent Corner Restoration

Year of search 3/1975 By C.R. Krause, USFS
Location filed: USFS Book 2, page 6
Monument: Found iron with cap up 4", in good condition 60' W of wood road N-S and witnesses as follow.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>Poplar</u>	<u>Maple</u>	_____
Diameter	<u>11"(1930)</u>	<u>18"(1930)</u>	<u>4"</u>	_____
Bearing	<u>N 4° E</u>	<u>N 45° W</u>	<u>S 48° W</u>	_____
Distance	<u>54.1'</u>	<u>40.9'</u>	<u>14.5' FSLP</u>	_____

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: Certificate of Location
Monument: Found GLO brass cap up 4", in good condition and witnesses as follow.
12" Red Oak, N 4° E, 54.1'(1930)
20" Aspen, N 45° W, 40.9'(1930)
32" White Pine, N 75° E, 191.40' scribed
10" Red Oak, S 28° E, 27.23' scribed
Steel Sign Post, North, 3.75'
Steel Sign Post, South, 4.05'


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. U 5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 577 Coordinates: X _____ Y _____
5116 Corner common to sections 29, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x36" l.p. w/ brass cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

5116
530/529
1930

Bearing Trees

Species	Bearing	Distance
<u>R. oak</u>	<u>Poplar</u>	
<u>6"</u>	<u>6"</u>	
<u>N 4 1/4 E</u>	<u>N 4 1/2 W</u>	
<u>82 LKS</u>	<u>62 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264958
Found GLO monument and BT's in good condition.
10" R. Oak S 28 E 27.23';
32" W. Pine N 75 E 191.40'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____