


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X 397040.23 Y 284295.69
N 1/4 8 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey
Year surveyed 1875
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. Pine N. Pine
Diameter 12" 12"
Bearing N15E S17E
Distance 38LKS 42LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Set 1x3/8" 1.1. w/ brass cap 4" below road surface
11/55
11/58
1930

Evidence of Subsequent Corner Restoration
Year of search 1925 By Miss. Hwy Dept.
R/W map in Recorder's office - Walker to Cass Lake
1.1. w/ brass cap 2226.0' w. of G

Bearing Trees, Reference Objects
Species N. Pine N. Pine
Diameter 9" 12"
Bearing N61 3/4 E S24E
Distance 89LKS 227LKS

Bearing Trees, Reference Objects

E-7 Subsequent Corner Restoration E 7
Year surveyed 1990 By WALT CURD
Location filed _____
Monument Found GLO BRASS CAP
N. PINE W. PINE W. OAK
20" 6" 3"
N 60 E S5W N45W
62.00 52.90 41.00
(1930 BT)

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERT. By WALT CURD 1990
Doc. # 325737

4/2001 USFS crew found iron pipe, brass cap gone, 1930 BT NE alive, others cut off.
4/2002 - file # 2002.009 CCSO found 1" ODIP in road, GPS location.