


Index No. 217

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
E1415 Corner common to sections 14,15



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Bearing Trees

Species	<u>N. Pine</u>	<u>N. Pine</u>	_____
Diameter	<u>12"</u>	<u>12"</u>	_____
Bearing	<u>S38W</u>	<u>S75E</u>	_____
Distance	<u>70 LKS</u>	<u>70 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By E. B. HORST

Location filed COUNTY BOOK "D" P. 68

Monument FIND STUMPS OF BOTH U.S. B.T.S SET STAKE

Evidence of Subsequent Corner Restoration

Year of search 1930 By GLO

End Stumps of both B.T.S Set 1136" 1/4 P. W. Brass
Cap 114
515/514
1930

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>	_____
Diameter	<u>5"</u>	<u>6"</u>	_____
Bearing	<u>N48.20E</u>	<u>N63W</u>	_____
Distance	<u>37.1'</u>	<u>53.6'</u>	_____

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	_____
Diameter	<u>7"</u>	<u>12"</u>	_____
Bearing	<u>S43E</u>	<u>S65.50W</u>	_____
Distance	<u>369 LKS</u>	<u>387 LKS</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 2000 By CCSO

Fnd. GLO Monument bent from rd. construction; no indication that it was moved. Position is 1.0' South of E/W fence lines. Located 23'± E of & C.R. 144

REF. TIES:

<u>12" Twin N. Pine</u>	<u>N 11° E</u>	<u>99.08'</u>
<u>5" J. Pine</u>	<u>S 78° E</u>	<u>17.44'</u>
<u>6" N. Pine</u>	<u>S 60° W</u>	<u>63.82'</u>

* distances are to dbl. hd. nails
6/14/00 - Re-set GLO Mon., flush w/ ditch bottom from ties.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____