


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. 215

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5TH Coordinates: X _____ Y _____
5/4 34 Corner common to sections 34



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Bearing Trees

Species NO B.T.S
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK B" P323327
Monument SET 4" TAM POST 5' LONG PROPERLY

Bearing Trees, Reference Objects

Species TAM DEAD TAM
Diameter 4" 3"
Bearing NRB-15E NSB-04W
Distance 53 LKS. 53.50'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

2-15

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEPHANSON - 1982
Doc. # 263909
Set 2" x 60" galvanized iron pipe with
marked brass cap.
5" Tamarack N70 W 23.80';
5" Tamarack N22 W 21.54';
4" Tamarack N20 E 14.17';
4" Tamarack N60 E 13.60';

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____