


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1874  
 Original monument Post

Species	Bearing	Distance
<u>Bl. Pine</u>	<u>5"</u>	<u>260 LKS</u>
<u>Bl. Pine</u>	<u>6"</u>	<u>337 LKS</u>
<u>Bl. Pine</u>	<u>7"</u>	<u>26 LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**  
 Year surveyed 1974 By PLM  
 Location filed Sec. of State  
 Monument Find 2" lip. w/ brass cap Set by RLS # 3628 in 1958 also find  
Bl. Pine stub 54W 6 LKS

**Evidence of Subsequent Corner Restoration**  
 Year of search 1958 By Pete Meyer  
Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

**Bearing Trees, Reference Objects**  
<sup>1958</sup> RLS # 3628

Species	Diameter	Bearing	Distance
<u>Tam</u>	<u>7"</u>	<u>S56E</u>	<u>156 LKS</u>
<u>Tam</u>	<u>15"</u>	<u>S22E</u>	<u>94 LKS</u>
<u>R. Pine</u>	<u>25"</u>	<u>S51W</u>	<u>278 LKS</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>R. Pine</u>	<u>20"</u>	<u>S51W</u>	<u>183.5'</u>
<u>Tamarack</u>	<u>14"</u>	<u>S22E</u>	<u>62.0'</u>
<u>Tamarack</u>	<u>6"</u>	<u>S56E</u>	<u>103.0'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_