


Index No. N 5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument Post

Species	Bearing	Trees	
<u>Y. Pine</u>	<u>Aspen</u>	<u>Aspen</u>	<u>Aspen</u>
<u>20"</u>	<u>6"</u>	<u>3"</u>	<u>6"</u>
<u>N85W</u>	<u>N75E</u>	<u>S30E</u>	<u>S53W</u>
<u>5 LKS</u>	<u>35 LKS</u>	<u>20 LKS</u>	<u>24 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1933 By GLO
 Location filed Sec of State
 Monument End SW BIT - now 18" and remains of NW 1/4 BIT. Set concrete man 24" long 6" dia w/ brass cap

Species	Bearing	Trees, Reference Objects	
<u>R. oak</u>	<u>B. oak</u>	<u>R. oak</u>	<u>R. oak</u>
<u>7"</u>	<u>8"</u>	<u>7"</u>	<u>7"</u>
<u>N49 1/2 E</u>	<u>S 81 3/4 E</u>	<u>S 74 1/2 W</u>	<u>N 54 W</u>
<u>58 LKS</u>	<u>72 LKS</u>	<u>46 LKS</u>	<u>79 LKS</u>

Evidence of Subsequent Corner Restoration
 Year of search 1966 By William Okerman
 Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>7"</u>	<u>N 65 W</u>	<u>30.55'</u>
<u>Oak</u>	<u>7"</u>	<u>S 46 W</u>	<u>25.1'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____