


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

		Bearing Trees	
Species	<u>Sugar</u>	<u>Sugar</u>	<u>Lynn Elm</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N63E</u>	<u>S40W</u>	<u>N81W S21E</u>
Distance	<u>12 LKS</u>	<u>9 LKS</u>	<u>14 LKS 37 LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1910 By JAMES MIDDLETON
 Location filed COUNTY BOOK "B" P. 577
 Monument FIND 4" OAK HUB SET FROM OLD GOVT B.T.S?
STUMP 6" SUGAR MAPLE S48E 9 LKS, 6" ELM S21E 37 LKS
AND Co. Rd. SURVAY B.T.S: 8" MAPLE NW T3, 70', 6" BLACK
SUN, 30" W. LINE STUMP SE 48.45'

Evidence of Subsequent Corner Restoration
 Year of search 4/01 By CCSO
Found Telspar post cap corroded
away, down 0.5', 3'± W, and 2'± N. of
E.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects			
<u>R. Oak</u>	<u>R. Oak</u>	<u>Cedar Post</u>	<u>P. Pole</u>
<u>10"</u>	<u>10"</u>		
<u>S48°E</u>	<u>N67°E</u>	<u>N47°W</u>	<u>S42°W</u>
<u>107.78'</u>	<u>74.63*</u>	<u>48.69*</u>	<u>48.14*</u>

*distance to double head nail

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument June 1982, A. Kerick #12266
Cert. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____