


T. 145 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SE 33 Corner common to sections 33, 34 and 4-144-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Burr Oak</u>	<u>Yellow Pine</u>	_____
Diameter	<u>10"</u>	<u>16"</u>	_____
Bearing	<u>N 1° E</u>	<u>N 58° E</u>	_____
Distance	<u>125 links</u>	<u>50 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3/1910 By J.W. Curo, LS 1428  
Location filed: Survey Record #237, Book A, page 605 and 608  
Monument: Set 2.5"x 48" galvanized iron pipe with cap  
No evidence of witness trees, set iron at proportionate position.

Evidence of Subsequent Corner Restoration

Year of search 6/1916 By J.F. Pomasel, LS 1728  
Location filed: Curo Book 62, image 167  
Monument:  
Level notes, indicate corner at 105+58.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 8/1930 By H.D. Craig, U.S. Surveyor, GLO  
Location filed: MN Hist. Soc., T144N R31W notes page 14  
Monument: Found 2" Cass County galvanized iron pipe flush with surface at intersection of roads E., W. and N. original witnesses destroyed during the construction of roads. 25" Norway Pine, N 69°45' W, 83 links(54.78')

Evidence of Subsequent Corner Restoration Found

Year of search 2002 By CCHD/SO  
Location filed: #2001.015  
Monument: Found 2" ODIP with plumber cap down 0.7', 2'+/-, S. and 2'+/-, E. of centerline centerline and witnesses as follows.  
8" W. Oak, N 24° E, 82.11'  
12" W. Pine, S 32° E, 35.12'  
Guy. Pole, S 54° W, 47.58'  
14" R. Oak, N 46° W, 103.28'

Circa 1933, J.A. Gjelhaug, Eng. CCC  
USFS Form 874-9  
Notes corner at intersection of roads and notes witness.  
16" N. Pine, N 69° W, 82 links(54.12') possible 1930 witness


5/1981, C. Krause, USFS  
T145N R31W Field Book 1, page 16  
Found 2.5"x 48" iron pipe with cap, bent and split. Had shop straighten and weld. Reset down 1.0' with rocks around pipe, in road intersection, Co. Rd. E-W, Twp. Rd. N. and witnesses.  
8" W. Oak, N 59° W, 123.60' nail in side  
7" W. Oak, N 41° W, 147.70' nail in side  
6" W. Oak, N 21° W, 161.07' nail in side  
Tele. Pole, N 45° W, 51.46' FSLP

Index No. 213

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SE83 Corner common to sections 33,34



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1871  
Original monument rest

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>Br. oak</u>	<u>4 Pine</u>
Diameter <u>10"</u>	<u>16"</u>
Bearing <u>N1E</u>	<u>N58E</u>
Distance <u>125 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1913 By John Curo  
Location filed County Book "A" P. 605-611  
Monument Set 2 1/2 x 48" GALV. 1. P. W/ cap

Year of search 1930 By GLO  
Found 2" Cass Co. 1 1/2" W/ galvanized cap  
33/34  
145-31

1916 - Panuse - microfilm - roll 105 BX62 P23  
Find corner

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

<u>N. Pine</u>	_____
<u>25"</u>	_____
<u>N69-45W</u>	_____
<u>83 LKS</u>	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search 2002 By CCSO #2001.015  
Found 2" ODIP/w plumbers cap, down 0.7,  
2 ± S. and 2 ± E of 8 E.

<u>8" W. OAK</u>	<u>N 24° E</u>	<u>82.11</u>
<u>12" W. PIPE</u>	<u>S 32° E</u>	<u>35.12</u>
<u>Guy Pole</u>	<u>S 54° W</u>	<u>47.58</u>
<u>14" R. OAK</u>	<u>N 46° W</u>	<u>103.28</u>

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_