

Homebrook Twp.
Bellevue

Down 137. N. R. 31. W. 5 P. 17.

ROAD No.

SURVEYOR'S REPORT.

Filed the 13 day of

June A. D. 1905

L. E. Guffert
County Auditor.

By _____ Deputy.

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

A horizontal line is drawn between rows 23 and 26, labeled "new Road" with a bearing of $N 9^{\circ} 28'$.
 A vertical line is drawn between columns 33 and 34, labeled "New Road" with a bearing of $S 10^{\circ} 38'$.
 A vertical line is drawn between columns 34 and 35, labeled "New Road" with a bearing of $N 9^{\circ} 45'$.
 A horizontal line is drawn between rows 26 and 35, labeled "New Road" with a bearing of $S 8^{\circ} 11'$.

To the Board of ^{Town} Supervisors, (Bangor) County of Dodge, Minnesota.

The undersigned Wm. A. Hallett having been employed by you to make a survey of a Road in said Township would report that the following is a correct survey thereof, as made by me under your direction, to-wit:

Station	BEARING TREES	Course	Distance	REMARKS
1	N.W. corner of sec.	34 South	1 mile.	To town line.
2	" " " "	35 " "	" "	" " " "
3	N.W. " "	26 East	2 miles.	" " "
4	East 1/4 post.	25 North 1/2	" "	To N.E. corner of sec. 24.
5	S.E. corner of sec.	35 West 1/2	" "	... south 1/4 post. 38
<p>At section corner of sec. 34 & 35 on town line T. 137. R. 31. I set oak post 4x4, 12 ft in ground, 2 ft out. Marked 34 & 35 and private mark *. 10 links north, east, and west. I dug pits and placed rocks in each.</p> <p>At north 1/4 sec. cor. of sec. 3. 136. 31. I set oak post marked road, and *.</p> <p>At 1/4 section corner south side of sec. 35. 136. 31. I set oak post, marked 1/4, S. 35. *</p> <p>At the N.E. corner of sec. 3. 136. 31. I set oak post. 3 ft in ground. Marked S. 2, S. 3, and *.</p>				