

Supervisor's copy

U. S. Department of Agriculture
FOREST SERVICE

P
97

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 25W A¹/₂P Mer.

SC 1/16 Corner common to Sections

20, _____, and _____

Corner consists of a iron pin (not) in place

State condition Good

Dimensions above ground A inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>None</u>		
N	W	S	E

	<u>None</u>		
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

54

	<u>None</u>		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by County

Engineers


J. H. Ahrenholz
(Signature)

Junior Forester
(Title)

6/19/37
(Date)

Corner again.
 Corner located under wire fence.
 separating Martin's place from
 Government land. No bearing trees
 located.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears due West
 side of Post
 tree 4 inches diameter, on the West
 Metal Location Poster is on a Cedar post



(Make sketch of topography near Corner)

T. 58N R. 25W 9th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W A 16 P Mer.

SC 116 Corner common to Sections

20, and

Corner consists of a iron pin (not) in place

State condition Good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		None	
N	W	S	E

		None	
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		None

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by County

Engineers

L. H. Ahrensberg

(Signature)


Junior Forester

(Title)

6/19/37 (Date)

Corner again.
 Corner located under wire fence
 separating Martin's place from
 Government land. No bearing trees
 located.

Give any further facts which will aid in finding this
 .03 chains distant.
 from which this Corner bears *clear West*
 side of *Post*
 tree 4 inches diameter, on the *West*
 Metal Location Poster is on a *Cedar Post*



(Make sketch of topography near Corner)

T. 58 N. R. 25 W. 4th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

8-7

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 4th P Mer.

SC 116 Corner common to Sections
20, _____, and _____

Corner consists of a iron pin (not) in place

State condition Good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>None</u>			
N	W	S	E

<u>None</u>			
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>None</u>			

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? N^o

If not, why? Corner established by
County engineers

J. H. Ahrensberg

(Signature)


Junior Forester

(Title)

6/19/37
(Date)

Corner again.
 Corner located under wire fence
 separating Morlin's place from
 Gernant land. No bearing trees
 located.

Give any further facts which will aid in finding this
 .03 chains distant.
 from which this Corner bears *due West*
 side of *Post*
 tree 7 inches diameter, on the *West*
 Metal Location Poster is on a *Cedar Post*



(Make sketch of topography near Corner)

T. 58 N R. 25 W 4th P Mer.