

U. S. Department of Agriculture

FOREST SERVICE

East MC on

Hunter

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-57 R. 25 Mer. 23-24Corner common to Sections
MC
1-36, andCorner consists of a Iron pipe (not) in place
State condition goodDimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Scrub</u>		

Species Birch RPDiameter 10 10Bearing N10E S15EDistance 1 chDo you believe this to be a genuine Land Office Corner? NoIf not, why? Set by county - 1954

Ralph H. Christensen
(Signature)

(Date)

D.F.P.

(Title)

f. type.

Cabin is 1 1/2 ch East and 30' South

Pipe is 6' North of D.M.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *logs B.T.*



(Make sketch of topography near Corner)