

U. S. Department of Agriculture
FOREST SERVICE

5-23424

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 25 W. 4th Mer.

Meander Corner common to Sections
12, and 13 (E. bank)

Corner consists of a Tamarack post ~~post~~ in place
State condition new

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

MC		MC	
S		S	
12		13	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		Rotted off at ground	
B T			

Species Tam. stump Tam. stump

Diameter 4" 8"

Bearing N61°E S29°E

Distance 0.11 ch. 0.33 ch.

Do you believe this to be a genuine Land Office Corner? **Yes**

~~Is not, why?~~ Remains of old corner post in place. Frozen in so I could not dig it out, but looked genuine.

Seth W. Peterson

(Signature)

Jr. Ass't. to Tech.

(Title)

4/19/38

(Date)



1 chain from SE edge.

Corner is in Black spruce swamp, about

Corner again.

Give any further facts which will aid in finding this

0.07 chains distant.

from which this Corner bears

side of spruce swamp

tree 4 inches diameter, on the southeast

Metal Location Poster is on a Black spruce

	Sec. 15		Sec.
	Sec. 12		Sec.

(Make sketch of topography near Corner)