

U. S. Department of Agriculture

FOREST SERVICE

EF-25

~~CHIPPEWA~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

Meander Corner common to Sections

12-59-26 and 7-59-26

Corner consists of a 3" ~~1 1/2" x 1 1/2"~~ ^{scribed post} ~~iron pipe~~ in place

State condition Good

Dimensions above ground 56 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|--------------|---|-------------|
| | M.O. S 12 | | M.O. S 7 |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------|--|--------|--|
| M.C.S7 | | M.C.S7 | |
| B.T. | | | |

Species Aspen Fallen Cedar

Diameter 6" 8"

Bearing S30° E S31° E

Distance 87 lks 49 lks

Do you believe this to be a genuine Land Office Corner? Y.

If not, why? Re-set by County from old cedar B. T. which is still in.

Ruthen Johnson
(Signature)

11/7/39


(Date)

Squad Foreman

(Title)

Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 chains distant.

Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

E, F-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W -25 4th P Mer.

Meander Corner common to Sections

12, and 7

Corner consists of a Aspen post (post) in place

State condition Good 2"x 22" Ir. Pipe

Dimensions above ground post 40 Iron pipe 2 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. Bt.

T59N R25W M05 7

B.T.

Mod. New B.T.

M.C. S 7

B.T.

Species Spruce Dead Aspen

Diameter 5" 6"

Bearing S31° E S30° 45' E

Distance 48 86

Do you believe this to be a genuine Land Office Corner?

If not, why?


J. A. Gjalhaug (Signature)

6/24/37 (Date)

Jr. CIVIL ENG.

opened up true line from ² corner
 common to sections 12 and 7 North to
 N.C. in edge of Lake.
 Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59N R. 26W 25W 4th P. Mer.

U. S. Department of Agriculture

FOREST SERVICE

EF-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

Corner common to sections

12, and 7

Corner consists of a ~~open post~~ (not) in place

State condition ~~2" x 22" Ir. Pipe~~ Good

Dimensions above ground ~~Post 40 Iron pipe~~ inches

Sketch grooves, letters, figures, or notches, on proper face of edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. Bt. T59 R25N MC3 7 B.T.



Mtd. New B.T. M.C. S 7 B.T.

Species Spruce Dead Diameter 5" Bearing S31°E Distance 48

Aspen Diameter 6" Bearing S30°45'E Distance 85

Do you believe this to be a genuine Land Office Corner? If not, why?

J. A. Einthaus

6/24/37

Jr. Civil Eng.

Opened up true line from ⁴ corner common to sections 12 and 7 north to M.C. in edge of lake.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th p Mer.

Meander Corner common to Sections

12, and 7

Corner consists of a Aspen post (not) in place

State condition Good

Dimensions above ground Post 40 Iron pipe 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

IBR

Orig. B.T.

Mtd. New B.T.

| |
|-------|
| T59N |
| R25W |
| MCS 7 |

| |
|--|
| |
|--|

| |
|------|
| M.C. |
| S 7 |

| |
|--|
| |
|--|

| |
|------|
| B.T. |
|------|

| |
|--|
| |
|--|

| |
|------|
| B.T. |
|------|

| |
|--|
| |
|--|

Species Spruce Dead Aspen

Diameter 5" 6"

Bearing S31°E S30°45'E

Distance 48 86

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

J. A. Gjelhaug

(Signature)

Ir. Civil Eng.


(Title)

6/24/37

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

Opened up true line from $\frac{7}{8}$ corner common to sections 12 and 7 North to M.C. in edge of lake.



(Make sketch of topography near Corner)

T. 59N R. 26W 25W 4th P. Mer.

U. S. Department of Agriculture

FOREST SERVICE

E, F-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4 th Mer.

Meander Corner common to sections 12-59-26 and 7-59-25

Corner consists of a 3" x 6" iron pipe (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|-------------|---|-------------|
| | M.C. S12 | | M.C. S 7 |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------|--|--------|--|
| M.C.S7 | | M.C.S7 | |
| B.T. | | | |

Species Aspen Fallen cedar

Diameter 6" 8"

Bearing S30°E S31°E

Distance 87Lks 49 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Re-set by County from old cedar B. T. which is still in.


Arthur Johnson (Signature)

Squad Foreman

11/7/39

(Date)

(Title)



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4 th Mer.

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.