

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

2-15-

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 27 4 Mer.

1/4 Corner common to Sections  
15, and 22

Corner consists of a Stake (not in place)

State condition good

Dimensions above ground in lake inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_

Established by Fryviller's

H. Hamelain

(Signature)

12-15-39

(Date)


ccc

(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.  
 This corner located about  
 1/4 mi. East of  
 Section # 6

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

N-15  
 T. 60 R. 27  
 Mer. N-15