

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

J-23

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 26 5th. Mer.

N 1/4

Corner common to Sections

13, and 12

Corner consists of a wooden post (one) in place

State condition poor

Dimensions above ground 18" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>S</u>		<u>N</u>	
<u>1/2</u>		<u>1/2</u>	
<u>38</u>		<u>38</u>	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter NONE

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R. T. De Fant
Raymond T. De Fant

(Signature)

Jr. Civil Engineer

(Title)

2-26-40

(Date)

road.

It is located on the corner of the

Corner again.

Give any further facts which will aid in finding the

chain distant.

from which this Corner bears

South

side of


fence post

tree inches diameter, on the

South

Metal Location Poster is on a

fence post



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

J-23

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 26 5th. Mer.
 N 1/4 Corner common to Sections

....., 13, and 12
 Corner consists of a wooden post (~~rock~~) in place
 State condition poor

Dimensions above ground 18" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 1 12 SB		N 1 13 SB	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species
 Diameter
 Bearing N O N E
 Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

R. T. DeFaut
 Raymond T. DeFaut
 (Signature)

2-26-40
 (Date)

Jr. Civil Engineer
 (Title)

road.

It is located on the corner of the

Corner again.

Give any further facts which will aid in finding this


37 chains distant.

from which this Corner bears South

side of fence post

tree 8 inches diameter, on the South

Metal Location Poster is on a fence post



(Make sketch of topography near Corner)