

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

J-9

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5th. Mer.

Section

Corner common to Sections

8, 9, 17, and 16

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T141N R27W	T141N R27W	Fire Scarred	
	BT		

Species 3' Stump Cedar Stump

Diameter 8" 10" 8"

Bearing N29°W N13°W S6°E

Distance 52 L 68 L 71 L

Do you believe this to be a genuine Land Office Corner?

If not, why? Corner is in center of road

J. J. Vanola
 Jan 14, 1936 J. J. Vanola P-1

(Date)

(Title)

The corner is in the center of road
Due to the fact there is so much snow
on the new ground is frozen no effort
was made to unearth it.

Corner again.


Give any further facts which will aid in finding this
chain distant.

From which this Corner bears

side of

tree inches diameter, on the

Metal Location Foster is on a
OLD HIGHWAY 434



(Make sketch of topography near Corner)