

U. S. Department of Agriculture  
FOREST SERVICE

*posted E-1*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *29+28* *5* Mer.

*Sec 1011* Corner common to Sections

*6, 7, 1, and 12*

Corner consists of a *Not in* (not) in place

State condition *Bearing trees found*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>1</i>	<i>12</i>	<i>7</i>	<i>6</i>
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Sec<sup>11</sup></i>
<i>141</i>
<i>29</i>

--

<i>Sec<sup>7</sup></i>
<i>141</i>
<i>29</i>

--

<i>B.T.</i>
-------------

--

<i>B.T.</i>
-------------

--

Species *Oak* *Oak*

Diameter *12"* *13"*

Bearing *N. 45° E.* *S. 50° E.*

Distance *70' App.* *60' App.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*R. A. McEachern*

*4-2/35*  
(Date)

*E-1*

*E. L. Lintner*  
(Title)

