

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*Posted 3-17*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *28* Mer.

Section Corner common to Sections

*10, 11, 14, and 15*

Corner consists of a *Iron Pipe* (not) in place

State condition *Edge of Road*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter *NO BEARING TREES*

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*G. Sherman*

(Signature)

*3/14/32*  
(Date)

*Engineer*  
(Title)

UNITED STATES GOVERNMENT  
DEPARTMENT OF AGRICULTURE  
BUREAU OF LAND MANAGEMENT

SECS. 10-15.

Road running West between

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears **West**

side of **Post**

tree **5** inches diameter, on the **West**

Metal Location Poster is on a **Fence Post**



(Make sketch of topography near Corner)

Mer. J-17

T. 14.1 R. 28