

U. S. Department of Agriculture

FOREST SERVICE

172  
1329037

*Chippewa*

M-23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *29 W.* *5<sup>th</sup>* Mer.

*Q5 1/16* Corner common to Sections *13*, and

Corner consists of a *6" aspen post* (not) in place  
State condition *Good*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No.*

If not, why? \_\_\_\_\_

*Established by @@@ crew*

*Carl Steadland*

*July 1936*  
(Date)

*Carl Steadland*  
(Signature)

*Const. Fore.*  
(Title)

Corner again.

Give any further facts which will aid in finding this

chain's distant.

1.21

from which this Corner bears *N 20 E*

side of

tree *10* inches diameter, on the

*Map*

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

*M-23*

Mer.

*T 1st N R 29 W*