

U. S. Department of Agriculture

Z-13

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

Section Corner common to Sections

33, and 34

Corner consists of a (not) in place

State condition not in place

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S34-
			141-
			30
			B. T.

Species Tamarack

Diameter 9"

Bearing N40°W

Distance 88 lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? B. T. does not conform with

original notes. Apparently set by

County engineer.

Edward Panek
Edward Panek Jr.
(Signature)Jr. Forester, E-1
(Title)

3/11/38

(Date)

Corner again.

Give any further facts which will aid in finding this


0.88 chains distant.

from which this Corner bears S40°W

side of Section corner.

tree 9 inches diameter, on the N.E.

Metal Location Poster is on a tamarack



(Make sketch of topography near Corner)

T. 141 N R. 30 W 5th
 M~~2~~-13
 X-13