

U. S. Department of Agriculture

FOREST SERVICE

*Posted*  
27

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141<sup>140</sup> R. 31 5<sup>-</sup> Mer.

14 Corner common to Sections  
32, and 5<sup>-</sup>



Corner consists of a IRON PIPE (not) in place  
State condition GOOD

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? NO BEARING TREES FOUND.  
COUNTY SUBDIVIDED.

*David Pristidge*

(Signature)

3/28/25  
(Date)

*Estimator*  
(Title)

ROAD 1/2 CHAIN EAST

Corner again.

Give any further facts which will aid in finding this


CHAIN'S chains distant.

from which this Corner bears S 43° E

side of CORNER

tree 5 inches diameter, on the N.W.

Metal Location Poster is on a N. ASPEN



(Make sketch of topography near Corner)

T. 141 R. 31 Mer.