

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

P.  
 E9

NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 142N R. 22W Mer.

Section Corner common to Sections  
5, 4, 8, and 2

Corner consists of a Cedar post (not) in place  
 State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	R 27W	T 142N
5	8	59	54

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species ✓ \_\_\_\_\_

Diameter ✓ \_\_\_\_\_

Bearing ✓ \_\_\_\_\_

Distance ✓ \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

A. S. Matuya

(Signature)

Estimator

(Title)

4-3-35

(Date)

CORNERS OF THE SECTION

Corner again.


Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

~~5~~ inches diameter, ~~center~~ <sup>post</sup> is corner

Metal Location Poster is on a ~~corner~~ <sup>POST</sup>



Sketch of topography near Corner

T. 44 N. R. 27 W. 5 Mer. E-9

Form 8740 - Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 27W 5th. Mer.

section

Corner common to Sections

5, 4, 8, and 9

Corner consists of a cedar post (iron) in place

State condition good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

		R27W	T142N
S5	S8	S9	S4

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? \_\_\_\_\_

A.G. Matuza

(Signature)

Estimator

(Title)

4/3/35

(Date)

WATER RESOURCES DIVISION

FIELD NOTES

NO. 100

DATE

BY

TO

SECTION

TOWNSHIP

COUNTY

STATE

SECTION

TOWNSHIP

COUNTY

STATE

SECTION

TOWNSHIP

COUNTY

STATE

SECTION

TOWNSHIP

COUNTY

STATE

SECTION

TOWNSHIP

COUNTY

STATE

SECTION

TOWNSHIP


COUNTY

STATE

SECTION

TOWNSHIP

Metal Location Post is on a cedar post  
 5 inches diameter, near corner  
 from which this corner bears  
 certain distant  
 Company further facts which will aid in finding this  
 corner again.



(Make sketch of topography near corner)

Met. E-9