

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST *9th Lake T13*

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 29 5th Mer.

1/4

Corner common to Sections

27

28

Corner consists of a Wood post & G.L.O. Mon. (post) in place


State condition Post in poor condition.

Dimensions above ground (G.L.O.) 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S	1/4 S28		
B.T.	B.T.		

Species *dead* W. Cedar W. Cedar

Diameter 18" 15"

Bearing S83W Due E

Distance 7 lks. 96 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Edward Panek
Edward Panek
(Signature)

4/12/38
(Date)

Junior Forester, P-1
(Title)

Corner again.

Give any further facts which will aid in finding this


71 lks. ~~XXX~~ Assistant.

from which this Corner bears S 83 E

side of 1/4 corner

tree 18 inches diameter, on the West

Metal Location Poster is on a Cedar Stub



(Make sketch of topography near Corner)

T. 142 R. 29 5th Mer.