

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *31W* *5<sup>th</sup>* Mer.  
*Section* Corner common to Sections

*16, 17, 20, and 21*

Corner consists of a *Cop iron pipe (not)* in place  
State condition *good*

Dimensions above ground *2 1/2" x 1 1/8"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *None*

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*County resurvey corner*

*Dorman J. Sutton*  
(Signature)

*3-14-95*  
(Date)

*Engineer*  
(Title)

Corner again.

Give any further facts which will aid in finding this

chain distant.


from which this Corner bears

562°E

side of tree

tree 12 inches diameter, on the S E

Metal Location Poster is on a W.O.K



(Make sketch of topography near Corner)

Mer. N-9

5th

T. 142 N. R. 51 W.