

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*Chippewa*

NATIONAL FOREST

*R 21*

CORNERS OF THE PUBLIC SURVEY

T. *143* R. *21* *5th* Mer.

*Section* Corner common to Sections *23*, *24*, *25*, and *26*



Corner consists of a *Brass Rapid pipe* (not) in place  
State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *R. Oak* *R. Oak*

Diameter *8"* *7"*

Bearing *N55 1/2 W* *S41 E*

Distance *5 1/2 - lks.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadman*

(Signature)

*Const. Foreman*

(Title)

*Dec. 5 1934*

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 143 R. 31 S. 5 Mer. R-21