

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*Chippewa* NATIONAL FOREST *N24*

CORNERS OF THE PUBLIC SURVEY

T. *T143 N* R. *31 W* *5th* Mer.

*E 1/16* Corner common to Sections

*12*, and *24*

Corner consists of a *Brass capped pipe* (not) in place


State condition *Good*

Dimensions above ground *6"* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION.

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen* *W. Oak*

Diameter *7"* *12"*

Bearing *S20E* *N9W*

Distance *12 1/4 lks.* *13 lks.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*


(Signature)

*Const. Foreman*

(Title)

*Dec. 6-1934*  
(Date)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

Mer. N-21

R.

T.