

~~841-9~~  
 AZ-25

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 (144) R. 25 (26) 5th Mer.

Section 1, 6, 7, and 8

Corner consists of a 12 in. Pipe (w/), in place  
 State condition Good

Dimensions above ground 2.4" high inches


Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION: DIAGONAL POSITION:



Mount of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Weathered Top (or hole) in proper location  
 by United States Forest Service, U. S. Department of Agriculture  
 Distances in feet.



Species	<i>Tax.</i>	<i>1213</i>	<i>Tax.</i>
Diameter	<i>6"</i>	<i>6"</i>	<i>6"</i>
Bearing	<i>N.</i>	<i>S 85 E</i>	<i>S 71 E</i>
Distance	<i>25</i>	<i>10</i>	<i>21</i>

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_

*Earl J. Harty*

Z-25

