

U. S. Department of Agriculture

FOREST SERVICE

0-6

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/10 Corner common to Sections

20, and

Corner consists of a metalting (not) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

W Ross Tucker

(Signature)


2-1-51

(Date)

(Title)

T. 145 R. 26  
 Mer. 5A

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Baldern  
 tree 6 inches diameter, on the SW  
 side of tree  
 this Corner bears \_\_\_\_\_ (Bearing) \_\_\_\_\_ (Distance)  
 Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_ is on  
 a \_\_\_\_\_ on the \_\_\_\_\_ (Name of road, trail, etc.)  
 located \_\_\_\_\_ chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor.  
 (Cross out nonapplicable)  
 Give any further facts needed to find Corner again:  
Blk. Co. Landed U.S.S. of corner