

U. S. Department of Agriculture  
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 30W 5th Mer.

MC 29958 AP 5 Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, and 34

Corner consists of a metal pipe (not) in place



State condition good

Dimensions above ground 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Birch B. Spruce

Diameter 8" 10"

Bearing S15W SKK

Distance 20 lks 75 lks

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Harold Heman  
(Signature)

Dec. 17, 1938

(Date)

(Title)