

U. S. Department of Agriculture
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 30W 5th Mer.

MC-28953-AP-5 Corner common to Sections
_____, _____, and 24

Corner consists of a metal pipe (not) in place
State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			<u>24</u>
N	W	S	E

<u>24</u>	<u>24</u>		
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>S. 24</u> <u>SWC</u> <u>A.P. 4</u>		
	<u>B.T.</u>		

Species N. Birch B. Spruce
 Diameter 8" 10"
 Bearing S16W SSE
 Distance 20 lks 75 lks

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Harold Hennas
(Signature)

Dec. 17, 1933

(Date)

(Title)