

U. S. Department of Agriculture  
FOREST SERVICE

E-9

C. P. P. & W. 2 NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

Section Corner common to Sections  
4, 5, 8, and 9

Corner consists of a N. L. O. (~~not~~) in place  
State condition

Dimensions above ground Underground inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

Sec	Sec	Sec	Sec
5	8	9	4
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

146-30  
Sec 5

146-30  
Sec 4

no  
marks

146-30  
Sec 9

B.T.

B.T.

B.T.

B.T.

Species A A Elm OAK  
Diameter 1 1/4" 10" 12" 4"  
Bearing N 45° W N 40° E S 30° W S 40° E  
Distance 80 96' 80 60

Do you believe this to be a genuine Land Office Corner? ...  
If not, why?

M. J. Murphy  
(Signature)


12/5/34  
(Date)

(Title)

E-9

Corner again.  
Aluminum pole located on  
south side front road of  
corner

Metal Location Poster is on a  
tree 14 inches diameter, on the  
side of road.  
from which this Corner bears  
80' chains distant.  
N 45 W



(Make sketch of topography near Corner)

T 146 R 30 Mer. E-9