

U. S. Department of Agriculture
FOREST SERVICE

7
022

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W S. 54 Mer.

1/16 #3 Corner common to Sections
....., and 24

Corner consists of a iron pipe + 4" Post (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 24		S 24	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16 #3</u>	<u>1/16 #3</u>		
<u>B.T</u>	<u>B.T</u>		

Species Pine Str. W. Pine

Diameter 22" 6"

Bearing N 18° E S 92° E

Distance 53.0 Lks 58.0 Lks

Do you believe this to be a genuine Land Office Corner? no

If not, why? Set by county survey

P.T.'s have county corner numbers
scribed on them

M. Markbeck


(Signature)

(Date)

(Title)

FOREST SERVICE

RECEIVED
JUL 11 1937
U.S. FOREST SERVICE



(Make sketch of topography near Corner)

T. 144N R. 25W Mer.

Metal Location Poster is on a *Baldern* tree inches diameter, on the *NW* side of *Tree* from which this Corner bears *N 76' W* chains distant.

Give any further facts which will aid in finding this

Corner again.

Notes on location poster taken from *S&W Johnson Survey*

U. S. Department of Agriculture

FOREST SERVICE

0-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 48 N R. 25 W S. 24 Mer.

1/16 #3 Corner common to Sections
and 24



Corner consists of a iron pipe 4" Post (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Pine Sp. W. Pine

Diameter 22 6"

Bearing N 18° E S 42° E

Distance 53.0 Lks 58.0 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Not by County Surveyor

P.T.'s are same County Corner described on this


(Signature)

7/17/27 (Date)

St. Clark (Title)

(Make sketch of topography near Corner)

T. 148 N. R. 25 W. Sec. 54 Mer.



Metal Location Poster is on a

tree 4 inches diameter, on the NW

side of this

from which this Corner bears N 76° W

50 chains distant.

Give any further facts which will aid in finding this

Corner again.