

U. S. Department of Agriculture

FOREST SERVICE

X-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 26 5 Mer.

1/4 Corner common to Sections 32, and 33

Corner consists of an Iron Pipe (not) in place State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Grid for cardinal positions: N, W, S, E

Grid for diagonal positions: NW, SW, SE, NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid for sketching bearing trees and rocks

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

Lloyd H. Johnson (Signature)

2-12-34 (Date)

Surveyor (Title)

X-9

Sec. 33 Subdivided.

FROM CENTER ROAD.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N 83° E 54

side of

tree inches diameter, on the

Metal Location Poster is on a FENCE POST



(Make sketch of topography near Corner)

T. 149 R. 26 S. Mer.