

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

R 19

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 S. Mer.



Quarter Corner common to Sections  
23, and 26

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

G. Sherman

(Signature)

1-17-34  
(Date)

Engineer  
(Title)

R-19

-----

-----

-----

-----


-----

-----

-----

Corner again.  
 Lower was not found.  
 Deep snow, 13 ft. was found.  
 be found.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the west  
 Metal Location Poster is on a Tel. Post



T. 149 R. 27  
 Mer. R-19  
 (Make sketch of topography near Corner)