

U. S. Department of Agriculture

FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 28 5 Mer.

44 Corner common to Sections

1, and 12

Corner consists of a Post (not) in place

State condition

Dimensions above ground 4 1/2' Dia 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species TAM.

Diameter 10"

Bearing S 40° E

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

L. D. Johnson

(Signature)

Surveyor

1-10-38

(Date)

(Title)

E-23

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

~~side~~ MARKED $\frac{1}{2}$ S 5th NORTH.

~~3~~ inches diameter, on the ~~and~~ $\frac{1}{2}$ ft. high.

~~Metal Location Post is on a~~ CORNER IS



(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

P
E23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 5P Mer.

1/4 Corner Corner common to Sections
1, 12, and

Corner consists of a Stake (set) in place

State condition Fair

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 S		—	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Bearing trees destroyed by fire and rotted away if dry.

Field Man: Hammer by H.C. Moman

(Signature)

Oct. 15, 1935


(Date)

J.F.

(Title)

Metal Location Poster is on a *SPRUCE* tree *6* inches diameter, on the *SOUTH* side of *Sec. 11 n.e. - 12* from which this Corner bears *N 5° W on 7° Dec. 27* *41 mks* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 149 N. R. 28 W. 6 P. Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 5P Mer.
1/4 Corner Corner common to Sections
1, 12, and

Corner consists of a Stake (not) in place
State condition Fair

Dimensions above ground 18 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

1/4			
S		-	
N	W	S	E

NW	SW	SE	NE

Mound of is located
Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species
Diameter
Bearing
Distance

Do you believe this to be a genuine Land Office Corner? yes
If not, why?

Bearing trees destroyed by fire
and rotted away if dry

Field Man: Harvey by N.C. Norman
(Signature) J.F.
Oct. 15, 1925 (Date) (Title) E-23

Corner again.

Give any further facts which will aid in finding this


27 links chains distant.

from which this Corner bears N5.0W on 7° Dec.

side of section 1-12

tree 6 inches diameter, on the South

Metal Location Poster is on a Spruce



Make sketch of topography near Corner

T. 149 N. R. 28 W. 5 P. Mer.