

U. S. Department of Agriculture  
FOREST SERVICE

R-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14<sup>o</sup> N. R. 31 W. 5th Mer.

1/4 Corner common to Sections

23, and 26

Corner consists of a Stake (not) in place

State condition Very Poor

Dimensions above ground Laying down inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

1/4		1/4	
S.		S.	

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Bearing trees burned over:			
Not to be found.			

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Swartz

Swartz

(Signature)

Enrollee

(Title)

4/23/36

(Date)


R-19

Metal Location Poster is on a Balsam tree 8 inches diameter, on the NE side of Tree

from which this Corner bears N. 73° 30' E. 74 chains distant.

Give any further facts which will aid in finding this Corner again.

Put new stake where old stake was found.



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th Mer. R-19