

U. S. Department of Agriculture
FOREST SERVICE

124

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 31 W. 5th Mer.

#8 - 1/16 Corner common to Sections
25, and



Corner consists of a Ironwood (not) in place
State condition Good.

Dimensions above ground 2 x 3 x 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Alm

Diameter 12"

Bearing N. 26° W.

Distance .10 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Bowman

E. Bowman

(Signature)


Enrollee

4/1/36

(Date)

(Title)

Metal Location Poster is on a Alm
 tree 12 inches diameter, on the South
 side of Tree
 from which this Corner bears S. 26° E.
10 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

124

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 31W Mer.

Corner common to Sections
25, _____, and 16 * 8

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|------------------------------|--|--|--|
| Pieces of scribes visible | | | |
| | | | |

Species ELM _____

Diameter 11 _____

Bearing NW _____

Distance ? _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Resurvey - subdivision


R. H. Christopherson
(Signature)

2-20-49
(Date)

D. F. T.
(Title)

Corner again.
 Placed control peg on fault
 shown. 3 chs south of corner
 post. Deep snow did not hold for
 362 ft. line from corner post to
 road 50' south of corner post
 control peg on line.

Give any further facts which will aid in finding this
 chains distant.
 ?
 from which this Corner bears
 ?
 side of
 tree 11 inches diameter, on the 50' ch
 Metal Location Poster is on a 15' m



(Make sketch of topography near Corner)

T. H. G. R. 31
 Mer.