

CORNER

RESTORATION

CORNER  
RESTORATION

151  
T~~HE~~ N

A260

FIELD BOOK  
32 0012  
BOOK # 1

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

1 2

Z-21 SECTION CORNER COMMON  
TO SECTION 35 & 36

FROM ORIGINAL SURVEY OF 1898 BY  
JOHN E. MULLIGAN

80.00 SET SECTION CORNER POST

10" 12"

CEDAR CEDAR

N 40 W N 40 E

6.6' 17.8'

1/2/64

KOOSKICHING COUNTY SURVEY FOUND  
BOTH BT'S IN GOOD CONDITION &  
SET A 1 1/2" X 4 1/2' PIPE WITH "AL"  
CAP.

5/8/79 FOUND ABOVE CAP & NW  
BT NOW A WINDFALL, NE, BT - GOOD.

MJ

1/4/80 Bill O'son, M. Harrison

Found Kooskiching Co. Monument mtd:

1 1/2" I.P. w/ 3" cap up 1.5'

Found 2 scuffed B.T.'s

14" Cedar N 48 E 17.29'

(down) 16" Cedar N 44 W 7 ft

1/4/80

Took 2 new B.T.'s:

mtd.

8" Cedar N 48 W 32.20' T. 51 N P. 2 W S 35 BT

14" Cedar N 6 W 75.1 N' T. 51 N P. 2 W S 35 BT

Steel Sign Post 4.5' East

Entered in this book 1/29/81 by MJH

1898  
3536

Z-21 SECTION CORNER COMMON  
TO SECTION 35 & 36  
FROM ORIGINAL SURVEY OF 1898 BY  
JOHN E. MULLIGAN

80.00 SET SECTION CORNER POST

10" 12"

CEDAR CEDAR

N 40° W N 40° E

6.6' 17.8'

1/2/64

KOOCHICHING COUNTY SURVEY FOUND  
BOTH BT'S IN GOOD CONDITION &  
SET A 1 1/2" X 4 1/2" PIPE WITH "AL"  
CAP.

5/8/79 FOUND ABOVE CAP & NW  
BT NOW A WINDFALL, NE, BT-GOOD.

MAZ

11/4/80 Bill Olson, M. Harrom

Found Koochiching Co. Monument Mkd:

1 1/2" I.P. w/ 3" cap up 1.5'

Found 2 scribed B.T.'s

14" Cedar N 48° E 17.29'

(down) 16" Cedar N 44° W 7 FT

27

Marcell Survey

11/4/80

B. Olson  
M. Harrom

CORNER NOTES

T151N R26W Section Cor 35 | 36  
FD. KOOCHICHING CO. MON MKD:  
1 1/2" I.P. w. 3" CAP UP 1.5'

151 26  
35 | 36

FD. 2 Scribed BT's:

14" Cedar N 48° E 17.29' scribed

(DOWN) 16" Cedar N 44° W 7 FT. scribed

TOOK 2 New BT's:

8" Cedar N 48° W 32.20' scribed

14" Cedar N 6° W 75.11' scribed

Set STEEL SIGN POST 4.5' EAST w. F.S. 54-9



Remainder of  
Book -

Blank  
Pages