

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 21, Township 141, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 7/8/80 found a marked GLO brass cap monument in good condition up 5".
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

263902

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Harry A. Stearns
SIGNATURE

4-30-82
DATE

Registration No. 12684

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:20 A.M. on the 22 day of July A.D., 1982

County Recorder Beverly Herdreich

By MS, Deputy

DOCUMENT NO. 263902

Statement of Evidence:

- 1873 U.S. General Land Office survey (set wood post) for this corner and marked the following bearing trees: 20" Y. Pine N 39 E 32 links and 18" Y. Pine S 34 W 35 links.
- 1918 U.S. General Land Office dependent resurvey reestablished this corner from the marked stump of a 16" Y. Pine N 39 E 32 links. No evidence was found of the SW bearing tree. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 5" N. Pine N 89-30 E 203 links and 10" R. Oak N 59-45 E 196 links.
- 1980 USFS technician Gary Brama found the GLO brass cap monument in place in good condition. Remains of the 1873 bearing tree stump with part of base blaze visible to the NE was found. No evidence was found of the 1918 bearing trees. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 3.75' east and west from the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1981 On Dec. 29, I visited this corner and found items as per the 1980 USFS report. I believe there may still be evidence of the 1918 bearing trees that should be checked further.
- 1982 On April 21, USFS technician C. Krause found the 1918 N. Pine bearing trees as follows: 22" N. Pine N 60 E 129.4' and at N 89 E 134.0' found oak stump hole. From this it appears that the bearings and distances were reversed in the field notes of the 1918 survey.
- 1982 I accepted the in place brass cap monument as marking the perpetuated position of the original corner.

41.1.16 - 35-85
SW-SW - Jan. 16
NE - NE - Jan. 21